

12444226Q0007 Questions and Answers

1. Confirm whether the repair is to be performed on-site in Richton, MS or if the unit can be transported off-site for shop repair.
Answer: The unit can be transported offsite.
2. Provide the current condition of the dozer, including operability and whether any disassembly has already been completed.
Answer: The dozer is currently operable.
3. Provide the serial number and exact configuration of the John Deere 700J LGP dozer.
Answer: T0700JX131341
4. Confirm whether the replacement final drive must be OEM or if rebuilt or aftermarket units are acceptable.
Answer: OEM
5. Clarify whether the existing final drive will be retained by the Government or returned as a core.
Answer: Returned to vendor as a core.
6. Provide any available photos of the equipment and the affected final drive.
Answer:



7. Please provide the exact location of the equipment needing repairs. So, I can have someone go and do an estimate?
Answer: 500 Salem Rd.
Richton, MS 39476
Note: Please call 601-383-5373 or 601-410-0985 beforehand to ensure someone is around to show them to the dozer. POC: Ryan Barnett.